




# 1993 Mercury Sable Wagon Alternator Replacement




Drive Belt Link



Old Alternator Installed



Combined Wrench Technique Applied for Drive Belt Tension Release



Replaced