





1993 Mercury Sable Wagon EGR Pressure Sensor Hose Repair



EGR (Exhaust Gas Recirculation) Pressure Sensor Hose Deteriorated (Left side hose)



New (Black) Prepared




Cut out Deteriorated Portion of Old Hose

Disconnecting cracked hose (Gray) from another port was hard because of the limited space.


After cutting out cracked portion of old hose (Gray), new hose (Black) was jointed by epoxy putty to old hose.



Epoxy Putty Jointed Two Hoses (Black & Gray)



Hose Repaired & Installed



Hose Repaired & Installed