

1993 Mercury Sable Wagon Engine Control Module Replacement




Old Engine Control Module Installed



OBDI scanner stopped the function occasionally because the serial data shift clock was not properly generated on ECM and provided to OBDI scanner.

Some strange behavior was observed when driving.


After replacing ECM, all the problems were gone.




Old (Left) & New (Right) Engine Control Module (Parts Side)




Old (Left) & New (Right) Engine Control Module (Interconnect Side)



Rear (Left) & Front (Right; with Connector) Engine Control Module Bay



Engine Control Module Support



Replaced