


Repair Vacuum Cleaner


Front wheel of Panasonic upright vacuum cleaner is driven by Type UB drive belt. The drive belt must be replaced when pulled apart.




Drive Belt Pulled Apart & New Belt



Drive Belt Removed



Replaced



Drive Belt Replaced Pulled Apart 1.5 Year Later Again

Drive belt seems to be fragile.