


## 2007 Pontiac Vibe Strut Boot Replacement




MacPherson Strut Spring Compressor

This tool is indispensable.

### (A) Driver's Side



Strut Boot Ripped Down



Removing

Because strut boot ripped down, bump stop (upper) and the chrome shaft of strut had been exposed.

Getting rust incurs strut function deterioration.

Tire, break fluid hose, stabilizer bar link, and two knuckle bolts must be loosened and detached.



Two Knuckle Bolts Removed



Strut Spring etc. Removed Apart



Assembled with New Boot, Dump Stop & Spring



Replaced

**(B) Passenger's Side**



Strut Boot Squashed



Assembled with New Boot, Dump Stop & Spring



Replaced