

1995 Toyota Camry Air Intake Tube Replacement



Before Replacement




Big Crack of Tube


OBDII scanner exhibits P0101, Mass air flow sensor measured excessive air intake (out of specified range).




Mass air flow sensor itself is working well (No need to replace).



Removed



Parts' Connection



Old (Top) & New (Bottom) Air Intake Tube



Old & New Air Filter



Replaced Air Filter (Bottom) & Tube (Center Right)

Because air filter is next to air intake tube to be replaced, the air filter was replaced as well.