

1995 Toyota Camry Drive Axle & CV Joint Replacement



Broken Stabilizer Link Set Bracket (Right) & Broken CV Joint Sleeve (Bottom)



Broken CV Joint & Replaced Stabilizer Link Set Bracket




A working stabilizer link set bracket was taken out from old Camry at junk yard for free.

Working Stabilizer Link Set Bracket & Old (Broken)

When CV (Constant Velocity) joint broke, stabilizer link set bracket broke at the same time. Six big and heavy metal balls in CV Joint fell down and scattered on the street.



New Drive Axle with CV Joint (Top) & Old Drive Axle with Broken CV Joint (Bottom)




Drive Shaft Lock Nut (Center)



Detached



Inboard Joint Sub-Assembly



Drive Axle Replaced



Stabilizer Link Set Bracket Replaced