

2007 Pontiac Vibe Splash Shield Replacement



Splash Shield Got Damage



Removing

When driving highway, a certain trash littered drove over collided splash shield. Due to the collision, the splash shield unlocked was rubbed by the driver's side tire rotated vigorously when driving. Then, the big hole was made on the splash shield and made it useless.



Old & New



Installed



Installed