

## 1993 Mercury Sable Wagon Engine Mount Replacement



Old Engine Mount



Releasing Engine Mount Nut from Engine Room

Three engine mounts (Front center, Left side, and Right rear) with cushion supports heavy engine.

This example shows the right rear engine mount.

The front center engine mount was most deteriorated.



Pushing up the Engine through Oil Pan



Top of the Engine Mount Released from Engine Chassis



Old & New Engine Mount



Replaced

Rubber cushion of old engine mount got deteriorated and the height is lower than new engine mount.