

1999 Toyota Avalon Gas Lid Hinge Repair




Gas Lid Hinge Flaked Away (Black metal basement shown at right center)



Gas Lid Hinge

The purpose of gas lid hinge is to open the gas lid sufficiently. Because the hinge flaked away from the basement, the gas lid became not opened (not popped up) sufficiently.



Hinge Pasted

3 years later, the hinge pasted was detached and lost due to deterioration of adhesive.

Gas Lid Hinge Replacement



Hinge had gone

No hinge is fatal. It incurs inability of refilling fuel because the gas lid never opens keeping locked. Normally, the fatal status is recognized at gas station dropping by for refill. I am sorry, it's too late...

Therefore, replacement to new hinge is much better than repair in terms of reliability.



New hinge (Up) & Plastic portion of old metal hinge gone (Down)



Attached